

令和6年能登半島地震被害状況調査結果

令和6年3月22日

| NO | 校下 地区 | 建築物 | | | | | | 工作物 | | 地盤 | | | | 海岸 堤防 | 河川 堤防 | 道路破損箇所 | | | | 断水箇所 | | | | 停電箇所 | | その他 |
|----|----------|-----|-----|-----|-----|----|-----|-----|----|-----|-----|-----|-----|----------|----------|--------|----|----|-----|------|------|-----------|----|------|------|---------------------------|
| | | 住宅 | | | その他 | | | 門 | 土塀 | 液状化 | 地滑り | 山崩れ | その他 | 破損 | 破損 | 市道 | 県道 | 国道 | その他 | 3日未満 | 3日以上 | 1週間 以上 | 長期 | 3日未満 | 3日以上 | |
| | | 全壊 | 半壊 | 損壊 | 全壊 | 半壊 | 損壊 | | | | | | | | | | | | | | | | | | | |
| 11 | 野 町 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |
| 12 | 弥 生 | | | | | | 1 | | | | | | | | | | | | | | | | | | | |
| 13 | 中村町 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 記載なし |
| 14 | 十一屋 | | | | | | | | | | 4 | | | | | | 1 | | | | 1 | | | | | |
| 15 | 泉 野 | | | | | | | | | | | | | | | | | | | | | | | | | 未提出 |
| 16 | 長坂台 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |
| 17 | 新竪町 | | | | | | 1 | | 1 | | | | | | | | | | | | | | | | | |
| 18 | 菊 川 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |
| 21 | 材 木 | | 4 | 30 | | | 6 | | 5 | | 3 | | | | | 11 | | | | 150 | 14 | | | | | |
| 22 | 味噌蔵 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 石垣の崩れ、塀のクラック |
| 23 | 長 町 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |
| 24 | 松ヶ枝 | | | | | | 3 | | | | | | | | | | | | | | | | | | | |
| 25 | 長土塀 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |
| 26 | 芳 斎 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 責任ある回答できない |
| 27 | 此 花 | | | 13 | | | 4 | 1 | | | | | | | | 6 | 6 | | | | | | | | | 外観からの判断 |
| 28 | 瓢 箪 | | | | | | 9 | | | | | | | | | | | | | | | | | | | |
| 31 | 馬 場 | | | 10 | | | | 2 | 2 | | | | | | | | | | | 1 | | | | | | 全調査していない |
| 32 | 浅野町 | | | 50 | | | 2 | | 17 | | | | | | | 20 | | | | | | | | | | 道路のひび割れ、ガス漏れ、神社被災 |
| 33 | 森 山 | | | | | | | | | | | | | | | | | | | | | | | | | 未提出 |
| 34 | 小 坂 | 7 | 12 | 255 | 0 | 2 | 56 | 3 | 32 | 22 | 29 | | 4 | | | 145 | 21 | 33 | 36 | 2 | 9 | | | 100 | | 各町会から報告集計 |
| 35 | 千 坂 | | | 136 | | | 5 | 1 | 4 | 5 | 1 | | | | | 143 | | | 55 | | | | | | | |
| 36 | 夕日寺 | | | 50 | | | 30 | | 20 | 3 | | 6 | 1 | | | | | | | | | | | | | |
| 41 | 諸 江 | | | | | | | | | 5 | | | | | | | | | | | | | | | | |
| 42 | 浅野川 | | | | | | | | 2 | | | | | | | 1 | | | | | | | | | | |
| 43 | 鞍 月 | | | 多数 | | | 蔵損壊 | | 多数 | | | | | | | 5 | | | | | | | | | | |
| 44 | 粟 崎 | 10 | 150 | 100 | | | | | | 2 | | | | | | 2 | | | 5 | | | 2 | | | | |
| 45 | 川 北 | | | 12 | | | 29 | | | | | | | | | 3 | | | | | | | | | | 板塀1箇所 |
| 46 | 大 浦 | | | 36 | | | 43 | | | 2 | | | | | | 3 | | | | | | | | | | 灯籠、ブロック塀は建築物に。マンホール、水道栓破損 |
| 51 | 米 丸 | | | 多数 | | | 多数 | | 不明 | 11 | | | | | | 11 | | | | 3 | | | | | | |
| 52 | 新神田 | | 1 | 3 | | | | | 1 | | | | | | | | | | | | | | | | | |
| 53 | 押 野 | | | | | | 1 | | | | | | | | | | | | | | | | | | | |
| 54 | 西南部 | | | 18 | | | | | | | | | | | | 多数 | 2 | | | | | | | | | |
| 55 | 三 和 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|-----|----|-----|------|---|---|-----|----|-----|----|----|----|----|---|---|-----|----|----|-----|-----|----|---|---|-----|---|------------------------|
| 61 | 三馬 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | | | | | | | | |
| 62 | 米泉 | | | | | | | | 2 | 1 | | | | | | 2 | | | | | | | | | | |
| 63 | 富樫 | | | | | | | | | | | | | | | 2 | | | | | | | | | | |
| 64 | 伏見台 | | | | | | | | 2 | | | | | | | 6 | | | | | | | | | | |
| 65 | 額 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 被害報告なし |
| 66 | 四十万 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 記載なし |
| 67 | 扇台 | | | 9 | | | 1 | | | | | | | | | 3 | 1 | | | | | | | | | |
| 71 | 長田町 | | | 64 | | | | | | 3 | | | | | | | 2 | | | 1 | | | | | | |
| 72 | 戸板 | | | 7 | | | 12 | 7 | 12 | | | | | | | 98 | 2 | | 6 | | | | | | | |
| 73 | 西 | 1 | | 17 | | | 1 | 1 | 3 | | | | | | | 39 | 20 | | | | | | | | | 西小学校プールの被害 |
| 74 | 二塚 | | 2 | 150 | | | | | 10 | 1 | | | | | | 1 | | | | | | | | | | 損壊は瓦、工作物の亀裂等、他灯籠200基倒壊 |
| 75 | 安原 | | | | | | 1 | | | | | | | | | 3 | | | | | | | | | | |
| 76 | 大徳 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 記載なし |
| 77 | 金石町 | | 2 | 13 | 1 | 1 | 4 | 1 | 6 | 5 | | | | | | 6 | | | | | | | | | | |
| 78 | 大野町 | | | | | | | | | | | | | | | | | | | | | | | | | 未提出 |
| 81 | 小立野 | | | | | | | | 1 | | | | | | | | | | | | | | | | | |
| 82 | 崎浦 | | | | | | | | | | | | | | | | | | | | | | | | | 未提出 |
| 83 | 内川 | | | 20 | | | 10 | | 2 | | 5 | 不明 | 不明 | | | | | | | | | | | | | 項目外に神社損傷あり |
| 84 | 犀川 | | | 1 | | | 1 | | | | | | | | | 1 | | | | | | | | | | |
| 85 | 湯涌 | | | 50 | | | | | | | 3 | 3 | 1 | | | 1 | | | | 1 | | | | | | 破損は住宅、その他合算 |
| 86 | 田上 | 4 | | | | | | | | 1 | 1 | | | | | 1 | | | | | | | | | | |
| 87 | 東浅川 | | | 7 | | | 5 | | 1 | | 1 | 1 | 4 | | 1 | 2 | | | | | | | | | | |
| 88 | 俵 | | | | | | | | | | | | | | | | | | | | | | | | | 未提出 |
| 89 | 医王山 | | | 117 | | | 22 | | | 3 | | 1 | 10 | | | 2 | | | | 9 | | | | | | |
| 91 | 森本 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 記載なし |
| 92 | 花園 | | | 50 | | | 4 | 5 | 2 | | 2 | | | | | 4 | 2 | | | | | | | | 2 | |
| 93 | 湖南 | | | 20 | 2 | | | 5 | 20 | 2 | | 2 | | | | 28 | | | | | | | | | | 道路破損6町会 |
| 94 | 薬師谷 | | | 42 | | | 3 | | 3 | | 5 | 3 | 7 | | 1 | 21 | | | | | | | | 1 | | 簡易水道の濁り |
| 95 | 三谷 | | 2 | 50 | 1 | | | | | | 1 | 2 | 50 | | | | | | 2 | | 1 | | | 12 | | |
| | | 22 | 173 | 1330 | 4 | 3 | 254 | 28 | 149 | 63 | 55 | 18 | 77 | 0 | 3 | 569 | 57 | 33 | 102 | 169 | 24 | 3 | 0 | 115 | 0 | |